

Name of Inspector: Mark A. Randazzo/O'Brien & Gere Engineers

Signature: 

Date of Inspection: November 22, 2016

Time of Inspection: 1215 hrs

**1) UPON COMPLETION, RETURN THIS FORM AND REPORT ALL IDENTIFIED PROBLEMS IMMEDIATELY TO THE WEP COORDINATOR.**

Key: Satisfactory – S Not Applicable – NA See Comment Section – C	AREAS SUBJECT TO INSPECTION		Additional Comments
	Southside of Bldg.	Northside of Bldg.	
Are there any hoses or signs of washing of vehicles or equipment (e.g., floats) outside?	S	S	
Interview one employee to assess compliance with this policy?			Name: Doug MacDonald – Mr. MacDonald indicated that he did not witness outside washing of equipment recently and that he understood the new policy.
Is there a posting inside the building notifying workers of proper process wastewater management?	C	C	Need to post a sign inside building.
Are there postings outside the building notifying workers of proper process wastewater management?	S	S	Posted outside to left of garage bays.
Other issues:			

**IMMEDIATELY CONTACT THE WEP COORDINATOR WITH ANY IDENTIFIED DEFICIENCIES AT (516) 204-5093. IF NOT AVAILABLE CONTACT SECURITY AT GATE 6 BACK STRETCH – (718) 641-4700 (ASK OPERATOR) OR AQUEDUCT MAIN SECURITY AT (718) 659-3511.**

